

# OEM Guide Page

## HWH SpaceMaker Equipment for **SELLERS MFG. INC. Vehicles**

(File: MR406790.DOC | Revised: 25APR17)

[> Printable PDF File](#)

**PROCEDURE:**

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> <i>AP11232</i>	<p><b>SINGLE CYLINDER ROOM EXTENSION – 25.0” STROKE – AP11231 KIT</b>  <b>SEE &gt; <a href="#">MR411000.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 – RAP90031 (25.0” STROKE)  REPLACES AP1911</p> <p>TUBE KIT_____ ITEM 2 – RAP90029 – REPLACES AP2369</p>
<b>MECHANISM</b> <i>AP11285</i>	<p><b>DUAL CYLINDER ROOM EXTENSION – 39.0” STROKE (WITH RACK SENSING VALVE)</b>  <b>AP11283 KIT</b>  <b>SEE &gt; <a href="#">MR411530.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 – RAP90007 (39.0” STROKE)  REPLACES AP1700</p> <p>HOSE ASSEMBLIES_____ ITEM 7 – RAP4159 (AP4159)  ITEM 8 – RAP4059 (AP4059)  ITEM 9 – RAP4827 (AP4827)  ITEM 10- RAP4061 (AP4061)</p>
<b>MECHANISM</b> <i>AP11289</i>	<p><b>DUAL CYLINDER ROOM EXTENSION – 49.0” STROKE (WITH RACK SENSING VALVE)</b>  <b>AP11288 KIT</b>  <b>SEE &gt; <a href="#">MR411530.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 – RAP90113 (49.0” STROKE)  REPLACES AP1054</p> <p>HOSE ASSEMBLIES_____ ITEM 7 – RAP4159 (AP4159)  ITEM 8 – RAP4060 (AP4060)  ITEM 9 – RAP5965 (AP5965)  ITEM 10- RAP7385 (AP7385)</p>
<b>MECHANISM</b> <i>AP11645</i>	<p><b>DUAL CYLINDER ROOM EXTENSION – 49.0” STROKE (WITH RACK SENSING VALVE)</b>  <b>AP11644 KIT</b>  <b>SEE &gt; <a href="#">MR411530.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b></p> <p>CYLINDER ASSEMBLY_____ ITEM 1 – RAP90113 (49.0” STROKE)  REPLACES AP1054</p> <p>HOSE ASSEMBLIES_____ ITEM 7 – RAP5351 (AP5351)  ITEM 8 – RAP4158 (AP4158)  ITEM 9 – RAP4059 (AP4059)  ITEM 10- RAP4074 (AP4074)</p>