

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "SPECIALTY VEHICLE SERVICE"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

|  |  |
|--|--|
| <b>MECHANISM</b><br><b>AP31745</b><br><b>AP31746</b> | <b>DUAL CYLINDER X-SLIDE - 30.75" STROKE (WITH SYNCHRONIZING CYLINDER) - AP31744 KIT</b><br><br><b>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</b><br><b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91352 (13.90" STROKE) - REPLACES AP27513<br><b>SYNCHRONIZING CYLINDER</b> _____ ITEM 3 - RAP90725 (5.460" STROKE) - REPLACES AP15043<br><b>TUBE KIT</b> _____ ITEM 2 - RAP91229 - REPLACES AP27587<br><b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672) |
|--|--|