

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "SUNDANCE COACH"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP15770 OR AP19305 AP19306	DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP15769 KIT SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90518 (36.5" STROKE) - REPLACES AP15251 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90474 (14.63" STROKE) - REPLACES AP12484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP17019 OR AP19313 AP19314	DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP17018 KIT SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90484 (24.5" STROKE) - REPLACES AP15252 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90472 (9.685" STROKE) - REPLACES AP13224 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP22862	SINGLE CYLINDER ROOM EXTENSION - 18.0" STROKE - AP22861 KIT SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)
MECHANISM AP23091	SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP23090 KIT SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)
MECHANISM AP25194 AP25195	VERTICAL ARM ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP25193 KIT SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91201 (10.172" STROKE) - REPLACES AP25030 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP91019 (3.935" STROKE) - REPLACES AP13180 HOSE ASSEMBLIES _____ ITEM 4 - RAP90386 (AP24643) ITEM 5 - RAP91236 (AP24647)