

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TAZWELL COACHES"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM</b> <b>AP20614</b> <b>AP20615</b>	<b>VERTICAL ARM ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP20613 KIT</b>  <a href="#">SEE MR41.2500 FOR DRAWING AND PARTS INFORMATION.</a> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91348 (14.30" STROKE) - REPLACES AP19378 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 6 - RAP90726 (5.75" STROKE) - REPLACES AP15042 <b>TUBE KIT</b> _____ RAP91223 - REPLACES AP19936 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90945 (AP18016) ITEM 5 - RAP91752 (AP14062)
<b>MECHANISM</b> <b>AP26333</b> <b>AP26334</b>	<b>VERTICAL ARM ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP26332 KIT</b>  <a href="#">SEE MR41.2500 FOR DRAWING AND PARTS INFORMATION.</a> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91200 (10.172" STROKE) - REPLACES AP24733 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 6 - RAP91019 (3.935" STROKE) - REPLACES AP13180 <b>TUBE KIT</b> _____ RAP91224 - REPLACES AP23196 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90386 (AP24643) ITEM 5 - RAP90428 (AP24642)