

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TESCHNER MOTORHOMES MFG."

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

| | |
|--|--|
| MECHANISM AP30055 | SINGLE CYLINDER ROOM EXTENSION - 30.0" STROKE - AP30054 KIT SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91805 (31.0" STROKE) - REPLACES AP28687 HOSE ASSEMBLIES _____ ITEM 4 - RAP90781 (AP24628) ITEM 3 - RAP90782 (AP24632) |
| MECHANISM AP36873 AP36874 | UNIVERSAL STRAIGHT OUT - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36020 KIT SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90472 (9.685" STROKE) - REPLACES AP13224 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818) |