

OEM Guide Page

HWH SpaceMaker Equipment for **TETON HOMES** Vehicles

(File: MR407405.DOC | Revised: 26APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP25518 AP25519	DUAL CYLINDER ROOM EXTENSION – 42.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP42751 KIT SEE > MR412011.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90477 (43.0” STROKE) REPLACES AP15668 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90447 (17.100” STROKE) REPLACES AP15687 TUBE KIT_____ ITEM 2 - RAP90481 - REPLACES AP15379
MECHANISM AP42740	SINGLE CYLINDER ROOM EXTENSION – 28.0” STROKE – AP42374 KIT SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91209 (30.125” STROKE) REPLACES AP28686 HOSE ASSEMBLIES_____ ITEM 3 - RAP24635 (AP24635) ITEM 4 - RAP24636 (AP24636)