

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TRIPLE E MFG." (PAGE 2 OF 3)

PROCEDURE: SEE "TRIPPLE E MFG." (PAGE 1 OF 3)

MECHANISM AP27483 AP27484	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 31.0" STROKE (WITH SYNC. CYLINDER) - AP27482 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91199 (32.0" STROKE) - REPLACES AP24262 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90442 (12.570" STROKE) - REPLACES AP16484 TUBE KIT _____ ITEM 2 - RAP91024 - REPLACES AP26587</p>
MECHANISM AP33254 AP33255	<p>DUAL CYLINDER ROOM EXTENSION - 29.125" STROKE (WITH SYNCHRONIZING CYLINDER)</p> <p>SEE MR41.2020 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90689 (32.0" STROKE) - REPLACES AP19616 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90690 (11.780" STROKE) - REPLACES AP17966 TUBE KIT _____ ITEM 2 - RAP91222 - REPLACES AP19736</p>
MECHANISM AP33429 AP33430	<p>DUAL CYLINDER ROOM EXTENSION - 16.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP33428 KIT</p> <p>SEE MR41.2020 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91607 (17.0" STROKE) - REPLACES AP33519 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90644 (6.390" STROKE) - REPLACES AP17436 TUBE KIT _____ ITEM 2 - RAP90658 - REPLACES AP18428</p>
MECHANISM AP33776	<p>DUAL CYLINDER ROOM EXTENSION - 31.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP34108 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91199 (32.0" STROKE) - REPLACES AP24262 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90442 (12.570" STROKE) - REPLACES AP16484 TUBE KIT _____ ITEM 2 - RAP91024 - REPLACES AP26587</p>
MECHANISM AP35843	<p>CYLINDER ASSEMBLY - 26.0" STROKE</p> <p>CYLINDER ASSEMBLY _____ RAP92523 (26.0" STROKE) - REPLACES AP35843</p>
AP37334	<p>STEP COVER CYLINDER ASSEMBLY - 26.0" STROKE</p> <p>OBSOLETE - REPLACED BY AP39433</p>
AP39433	<p>STEP COVER CYLINDER ASSEMBLY - 26.0" STROKE</p> <p>SEE MR41.5000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92109 (26.0" STROKE) - REPLACES AP39433 HOSE ASSEMBLY _____ ITEM 2 - RAP92111 (AP7359)</p>
MECHANISM AP39182 AP39183	<p>UNIVERSAL STRAIGHT OUT - 18.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41598 KIT</p> <p>SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92369 (6.30" STROKE) - REPLACES AP39267 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP40528 AP40529	<p>DUAL CYLINDER "HAT" ROOM EXTENSION - 24.0" STROKE (WITH SYNC. CYLINDER) - AP40527 KIT</p> <p>SEE MR41.2050 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90484 (24.5" STROKE) - REPLACES AP15252 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92275 (8.420" STROKE) - REPLACES AP39271 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>