

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TRIVAN TRUCK BODY"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP19281 AP19282	<p>FOUR CYLINDER ROOM EXTENSION - 70.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP46339 KIT</p> <p>SEE MR41.2006 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91189 (71.0" STROKE) - REPLACES AP17270 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92916 (13.730" STROKE) - REPLACES AP46340 SEE MR41.8004 FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS TUBE KIT _____ ITEM 2 - RAP91221 - REPLACES AP17321</p>
MECHANISM AP26043	<p>FLOOR CYLINDER LIFT - 10.172" STROKE - AP46460 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP91347 (10.172" STROKE) - REPLACES AP26043</p>
MECHANISM AP26889 AP26890	<p>DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39048 KIT</p> <p>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91799 (36.5" STROKE) - REPLACES AP23577 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90474 (14.630" STROKE) - REPLACES AP12484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>