

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TRIVAN TRUCK BODY TEXAS"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP19281 AP19282	FOUR CYLINDER ROOM EXTENSION - 70.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP46339 KIT SEE MR41.2006 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91189 (71.0" STROKE) - REPLACES AP17270 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92916 (13.730" STROKE) - REPLACES AP46340 SEE MR41.8004 FOR ADDITIONAL SYNC CYL REPLACEMENT PARTS TUBE KIT _____ ITEM 2 - RAP91221 - REPLACES AP17321
MECHANISM AP43166 AP43167	UNIVERSAL STRAIGHT OUT / LEVEL OUT - 30.0" STROKE (WITH SYNC. CYLINDER) - AP50057 KIT SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP93303 (10.540" STROKE) - REPLACES AP46064 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)
MECHANISM AP52786	PLATFORM LIFT WITH THREE CYLINDERS - 170" WIDE SEE MR41.4010 FOR DRAWING AND PARTS INFORMATION. CYLINDER W/ SEQ. VALVE ASSY. ____ ITEM 1 - RAP93139 (4.8" STROKE) - REPLACES AP44387 CYLINDER ASSEMBLY _____ ITEMS 2 - RAP93140 (4.8" STROKE) - REPLACES AP44395