

| | |
|--|---|
| MECHANISM AP40822 AP40823 | UNIVERSAL STRAIGHT OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP47756 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92075 (20.5” STROKE) REPLACES AP39251 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP92092 - REPLACES AP39321 HOSE ASSEMBLIES_____ ITEM 4 - RAP24631 (AP24631) ITEM 5 - RAP24637 (AP24637) |
| MECHANISM AP44727 AP44728 | UNIVERSAL LEVEL OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP42188 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92260 (2.75” LIFT) REPLACES AP38604 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638) |