

OEM Guide Page

HWH SpaceMaker Equipment for **VANTARE INTERNATIONAL** Vehicles

(File: MR408700.DOC | Revised: 09MAY17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP12355	<p>DUAL CYLINDER ROOM EXTENSION – 39.0” STROKE (WITH RACK SENSING VALVE) SEE > MR411536.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP90112 (39.0” STROKE) REPLACES AP11105</p> <p>HOSE ASSEMBLIES_____ ITEM 7 - RAP4073 (AP4073) ITEM 8 - RAP2446 (AP2446) ITEM 9 - RAP4074 (AP4074) ITEM 10- RAP10913 (AP10913)</p>
MECHANISM AP12356	<p>DUAL CYLINDER ROOM EXTENSION – 36.0” STROKE (WITH RACK SENSING VALVE) AP12361 KIT SEE > MR411534.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP90112 (39.0” STROKE) REPLACES AP11105</p> <p>HOSE ASSEMBLIES_____ ITEM 7 - RAP4728 (AP4728) ITEM 8 - RAP4158 (AP4158) ITEM 9 - RAP4074 (AP4074) ITEM 10- RAP4065 (AP4065)</p>
MECHANISM AP13210	<p>SINGLE CYLINDER ROOM EXTENSION – 25.0” STROKE – AP13211 SEE > MR411000.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP90031 (25.0” STROKE) REPLACES AP1911</p> <p>TUBE KIT_____ ITEM 2 - RAP90029 - REPLACES AP2369</p>
MECHANISM AP14143	<p>ROOM EXTENSION – 25.0” STROKE (CYLINDER ONLY) – AP14141 KIT</p> <p>CYLINDER ASSEMBLY_____ RAP90673 (25.0” STROKE) REPLACES AP14143</p>
MECHANISM AP16046 OR AP19294 AP19295	<p>DUAL CYLINDER ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYL.) AP14423 KIT SEE > MR412017.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP90487 (30.5” STROKE) REPLACES AP15184</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90641 (13.312” STROKE) REPLACES AP18180</p> <p>TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252</p>

MECHANISM AP13121 OR AP16047 OR AP19292 AP19293	DUAL CYLINDER ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYL.) AP13120 KIT SEE > MR412016.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90487 (30.5” STROKE) REPLACES AP15184 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90641 (12.312” STROKE) REPLACES AP18180 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP18288 AP18289	VERTICAL ARM ROOM EXTENSION – 24.0” STROKE (WITH SYNCHRONIZING CYL.) AP18287 KIT SEE > MR412505.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90426 (9.689” STROKE) REPLACES AP14028 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP90427 (3.815” STROKE) REPLACES AP14027 HOSE ASSEMBLIES_____ ITEM 4 - RAP49245 (AP49245) ITEM 5 - RAP49245 (AP49245)
MECHANISM AP19230 AP19231	DUAL CYLINDER ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYL.) AP13690 KIT SEE > MR412018.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90487 (30.5” STROKE) REPLACES AP15184 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90473 (12.155” STROKE) REPLACES AP13192 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252