

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "VARIO MOBILE"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP27853 AP27854	X-SLIDE ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP28167 KIT SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91208 (9.20" STROKE) - REPLACES AP27862 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90587 (3.455" STROKE) - REPLACES AP17199 TUBE ASSEMBLIES _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP33123 AP33124	X-SLIDE ROOM EXTENSION KIT - 18.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP33122 KIT SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91007 (8.10" STROKE) - REPLACES AP27723 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91006 (2.970" STROKE) - REPLACES AP27302 TUBE ASSEMBLIES _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)
MECHANISM AP37665	SINGLE CYLINDER ROOM EXTENSION - 18.0" STROKE - AP37664 KIT SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91667 (28.5" STROKE) - REPLACES AP28688 HOSE ASSEMBLIES _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)