

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "VISTA MOBILE TECHNOLOGY"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

| | |
|--|--|
| MECHANISM AP22227 AP22228 | DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP43260 KIT SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90518 (36.5" STROKE) REPLACES - AP15251 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90474 (14.630" STROKE) - REPLACES AP12484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252 |
| MECHANISM AP26889 AP26890 | DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP43259 KIT SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91799 (36.5" STROKE) - REPLACES AP23577 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90474 (14.630" STROKE) - REPLACES AP12484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252 |