

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "WAKERLEY MOTORHOMES"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP18960 AP18961	DUAL CYLINDER ROOM EXTENSION - 35.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP18959 KIT SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90476 (36.0" STROKE) - REPLACES AP15824 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90446 (14.425" STROKE) - REPLACES AP15763 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP22394 AP22395	DUAL CYLINDER ROOM EXTENSION - 36.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP22393 KIT SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP90518 (36.5" STROKE) - REPLACES AP15251 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90474 (14.630" STROKE) - REPLACES AP12484 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP24472 AP24473	DUAL CYLINDER ROOM EXTENSION - 23.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP24471 KIT SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92525 (24.0" STROKE) - REPLACES AP24476 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91017 (9.580" STROKE) - REPLACES AP24474 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP27489 AP27490	DUAL CYLINDER ROOM EXTENSION - 23.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP27488 KIT SEE MR41.2000 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92525 (24.0" STROKE) - REPLACES AP24476 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91017 (9.580" STROKE) - REPLACES AP24474 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252