

OEM Guide Page

HWH SpaceMaker Equipment for **LEISURE TRAVEL VANS Vehicles**

(File: MR403640.DOC | Revised: 10APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP15466	SINGLE CYLINDER ROOM EXTENSION – 31.0” STROKE – AP15465 KIT SEE > MR411000.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90103 (31.0” STROKE) REPLACES AP10740 TUBE KIT_____ ITEM 2 - RAP90029 - REPLACES AP2369
MECHANISM AP15475 AP15476	VERTICAL ARM ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP15469 KIT NO INFORMATION AVAILABLE