

OEM Guide Page

HWH SpaceMaker Equipment for **MARSHALL MACHINE SHOP** Vehicles

(File: MR403880.DOC | Revised: 18APR17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP18902</i>	<p>SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP37752 KIT SEE > MR411100.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682</p> <p>HOSE ASSEMBLIES_____ ITEM 3 - RAP50907 (AP50907) ITEM 4 - RAP16434 (AP16434)</p>
MECHANISM <i>AP25142</i> <i>AP25143</i>	<p>DUAL CYLINDER ROOM EXTENSION – 30.5” STROKE (WITH SYNCHRONIZING CYLINDER) AP37751 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP90971 (37.5” STROKE) REPLACES AP25201</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90442 (12.570” STROKE) REPLACES AP16484</p> <p>TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252</p>