

ROOM EXTENSION ASSEMBLIES GUIDE PAGE

"MONACO COACH CORPORATION" (PAGE 3 OF 4)

PROCEDURE: SEE "MONACO COACH CORPORATION" (PAGE 1 OF 4)

MECHANISM AP31690 AP31691	<p>LATERAL ARM ROOM EXTENSION - 16.0" STROKE - AP31689 KIT</p> <p>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91561 (AP24648) ITEM 5 - RAP91526 (AP24650)</p>
MECHANISM AP32165	<p>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP32164 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 4 - RAP90871 (AP24628) ITEM 3 - RAP90872 (AP24632)</p>
MECHANISM AP32003 AP32004	<p>UNIVERSAL SLIDE OUT - 17.625" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32002 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90439 (7.21" STROKE) - REPLACES AP16618 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP91421 (AP24818) ITEM 5 - RAP90872 (AP24632)</p>
MECHANISM AP32006	<p>SINGLE CYLINDER ROOM EXTENSION - 23.125" STROKE - AP32005 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 4 - RAP90384 (AP24630) ITEM 3 - RAP90320 (AP24634)</p>
MECHANISM AP32008 AP32009	<p>UNIVERSAL FLAT OUT - AP32007 KIT</p> <p>NO INFORMATION AVAILABLE.</p>
MECHANISM AP35083 AP35084	<p>X-SLIDE ROOM EXTENSION - 17.75" STROKE - AP35082 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91007 (8.100" STROKE) - REPLACES AP27723 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP90321 (AP24653) ITEM 5 - RAP91528 (AP24654)</p>
MECHANISM AP35907 AP35908	<p>X-SLIDE ROOM EXTENSION - 30.75" STROKE - AP35906 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91352 (13.90" STROKE) - REPLACES AP27513 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP90321 (AP24653) ITEM 5 - RAP91528 (AP24654)</p>
MECHANISM AP39096 AP39097	<p>DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39095 KIT</p> <p>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92509 (31.0" STROKE) - REPLACES AP39933 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92275 (8.42" STROKE) - REPLACES AP39271 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP39507 AP39508	<p>UNIVERSAL LEVEL OUT - 30.0" STROKE - AP39435 KIT</p> <p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 14 - CONTACT HWH CORPORATION TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818) CENTER LIFT CYLINDER _____ ITEM 16 - CONTACT HWH CORPORATION</p>