

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "MORRISON VIP COACH" (PAGE 3 OF 5)

PROCEDURE: SEE "MORRISON VIP COACH" (PAGE 1 OF 5)

MECHANISM AP27836 AP27837	<p>X-SLIDE ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP36357 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91208 (9.20" STROKE) - REPLACES AP27862 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90587 (3.455" STROKE) - REPLACES AP17199 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91553 (AP27857) ITEM 5 - RAP90800 (AP24640)</p>
MECHANISM AP28280 AP28281	<p>VERTICAL ARM ROOM EXTENSION - 21.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP28279 KIT</p> <p>SEE MR41.2500 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91198 (9.104" STROKE) - REPLACES AP23197 SYNCHRONIZING CYLINDER _____ ITEM 6 - RAP90587 (3.455" STROKE) - REPLACES AP17199 TUBE KIT _____ RAP91224 - REPLACES AP23196 HOSE ASSEMBLIES _____ ITEM 4 - RAP90386 (AP24643) ITEM 5 - RAP91236 (AP24647)</p>
MECHANISM AP32027 AP32028	<p>X-SLIDE ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32026 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91350 (11.400" STROKE) - REPLACES AP27865 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91701 (4.300" STROKE) - REPLACES AP30260 TUBE KIT _____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>
MECHANISM AP32030 AP32031	<p>X-SLIDE ROOM EXTENSION - 32.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32029 KIT</p> <p>SEE MR41.2670 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91210 (14.300" STROKE) - REPLACES AP29191 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90726 (5.750" STROKE) - REPLACES AP15042 TUBE KIT _____ ITEM 2 - RAP91230 - REPLACES AP29192 HOSE ASSEMBLIES _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91573 (AP32672)</p>
MECHANISM AP32431 AP32432	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 25.0" STROKE (WITH SYNC. CYLINDER) - AP33847 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP32870 AP32871	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 30.0" STROKE (WITH SYNC. CYLINDER) - AP32869 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP33322 AP33323	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 30.0" STROKE (WITH SYNC. CYLINDER) - AP51526 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>