

OEM Guide Page

HWH SpaceMaker Equipment for **NASHVILLE COACH WORKS** Vehicles

(File: MR404675.DOC | Revised: 19APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP10265</i>	DUAL CYLINDER ROOM EXTENSION – 34.0” STROKE – AP10468 KIT CYLINDER ASSEMBLY_____ AP2113 - CONTACT HWH CORPORATION FOR REPLACEMENT
MECHANISM <i>AP10476</i>	CYLINDER ASSEMBLY – 12.0” STROKE CYLINDER ASSEMBLY_____ AP10476 - CONTACT HWH CORPORATION FOR REPLACEMENT