

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "NEWELL" (PAGE 5 OF 5)

PROCEDURE: SEE: "NEWELL" (PAGE 1 OF 5)

MECHANISM AP21674 AP21675	<p><b>VERTICAL ARM ROOM EXTENSION - 22.0" STROKE (WITH SYNCHRONIZING CYLINDER)</b> AP24602, AP24841, AND AP26533 KITS</p> <hr/> <p><b>SEE MR41.2505 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - AP24522 (9.689" STROKE) - CONTACT HWH CORPORATION  <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 6 - RAP91016 (3.600" STROKE) - REPLACES AP24532  <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90801 (AP24658) ITEM 5 - RAP90321 (AP24653)</p>
MECHANISM AP24583	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP24582 KIT</b></p> <hr/> <p><b>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818  <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP91750 (AP13842) ITEM 4 - RAP91751 (AP16434)</p>
MECHANISM AP24830	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP21546 KIT</b></p> <hr/> <p><b>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818  <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP25597	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP25587 KIT</b></p> <hr/> <p><b>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818  <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP26228	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP24810 KIT</b></p> <hr/> <p><b>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818  <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>
MECHANISM AP26541	<p><b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP22364 KIT</b></p> <hr/> <p><b>SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</b>  <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90688 (27.0" STROKE) - REPLACES AP15818  <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)</p>