

MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP43554 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYL. _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP49617 AP49618	DUAL CYLINDER ROOM EXTENSION – 44.5” STROKE (WITH SYNCHRONIZING CYLINDER) AP49616 KIT SEE > MR412006.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP93355 (45.5” STROKE) REPLACES AP49718 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93356 (15.68” STROKE) REPLACES AP49697 TUBE KIT_____ ITEM 2 - RAP90481 - REPLACES AP15379