



<b>MECHANISM</b> AP18095 AP18096	<b>DUAL CYLINDER ROOM EXTENSION – 32.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP18094 KIT</b> <b>SEE &gt; <a href="#">MR41.2015.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90667 (32.5” STROKE) REPLACES AP18131 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.98” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP18095 AP18096 AP18608	<b>TRIPLE CYLINDER ROOM EXTENSION – 32.0” &amp; 18.0” STROKE (WITH SYNC. CYLINDER)</b> <b>AP18609 KIT</b> <b>SEE &gt; <a href="#">MR41.2015.HTML</a> AND <a href="#">MR41.1007.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ RAP90667 - (32.5” STROKE)-REPLACES AP18131 RAP90646 - (19.0” STROKE)-REPLACES AP18602 SYNCHRONIZING CYLINDER_____ RAP90668 - (12.98” STROKE) - 3 CYLINDER REPLACES AP18356 SYNC. CYL. PRESS. SWITCH_____ RAP90654 - 4000 PSI PRESSURE SWITCH REPLACES AP18676 TUBE KIT_____ RAP90480 - (AP13252) RAP90526 - (AP13592)
<b>MECHANISM</b> AP19251 AP19252	<b>DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP15211 KIT</b> <b>SEE &gt; <a href="#">MR41.2015.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP19257 AP19258	<b>DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP16496 KIT</b> <b>SEE &gt; <a href="#">MR41.2015.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP19392	<b>SINGLE CYLINDER ROOM EXTENSION – 24.0” STROKE – AP19391 KIT</b> <b>SEE &gt; <a href="#">MR41.1100.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP53984 (AP53984)
<b>MECHANISM</b> AP19409 AP19410	<b>DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP14371 KIT</b> <b>SEE &gt; <a href="#">MR41.2010.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP19926 AP19927	<b>DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP19925 KIT</b> <b>SEE &gt; <a href="#">MR41.2005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252

<b>MECHANISM</b> AP19929 AP19930	<b>DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP19928 KIT</b> <b>SEE &gt; <a href="#">MR41.2005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP20618 AP20619	<b>DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP20581 KIT</b> <b>SEE &gt; <a href="#">MR41.2011.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP20620 AP20621	<b>DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP20580 KIT</b> <b>SEE &gt; <a href="#">MR41.2011.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP20867 AP20868	<b>DUAL CYLINDER ROOM EXTENSION – 32.0” STROKE (WITH SYNC. CYLINDER)</b> <b>AP20866 KIT</b> <b>SEE &gt; <a href="#">MR41.2200.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90696 (36.0” STROKE) REPLACES AP19256 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.98” STROKE) REPLACES AP14301 HOSE ASSEMBLY_____ ITEM 2 - RAP24648 - REPLACES AP24648
<b>MECHANISM</b> AP20870 AP20871	<b>DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 34.5” STROKE (WITH SYNC. CYLINDER)</b> <b>AP20869 KIT</b> <b>SEE &gt; <a href="#">MR41.2200.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90696 (36.0” STROKE) REPLACES AP19256 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 HOSE ASSEMBLY_____ ITEM 2 - RAP24648 - REPLACES AP24648
<b>MECHANISM</b> AP20978 AP20979	<b>DUAL CYLINDER ROOM EXTENSION – 18.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP20977 KIT</b> <b>SEE &gt; <a href="#">MR41.2011.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90439 (7.21” STROKE) REPLACES AP16618 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP21156	<b>CYLINDER ASSEMBLY – 24.5” STROKE</b> CYLINDER ASSEMBLY_____ RAP93162 (24.5” STROKE)- REPLACES AP21156
<b>MECHANISM</b> AP21944	<b>SINGLE CYLINDER ROOM EXTENSION – 34.5” STROKE – AP21943 KIT</b> <b>SEE &gt; <a href="#">MR41.1008.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252

<b>MECHANISM</b> AP22788	<b>SINGLE CYLINDER ROOM EXTENSION – 25.0” STROKE – AP22787 KIT</b> <b>SEE &gt; <a href="#">MR41.1008.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP22919 AP22920	<b>DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 34.5” STROKE (WITH SYNC. CYLINDER)</b> <b>AP22918 KIT</b> <b>SEE &gt; <a href="#">MR41.2200.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90696 (36.0” STROKE) REPLACES AP19256 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368
<b>MECHANISM</b> AP24307	<b>SINGLE CYLINDER ROOM EXTENSION – 25.0” STROKE – AP24336 KIT</b> <b>SEE &gt; <a href="#">MR41.1100.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24635 (AP24635) ITEM 4 - RAP24632 (AP24632)
<b>MECHANISM</b> AP27070 AP27071	<b>LATERAL ARM ROOM EXTENSION – 21.0” STROKE (WITH TORSION BAR)</b> <b>AP27069 KIT</b> <b>NO INFORMATION AVAILABLE.</b>
<b>MECHANISM</b> AP29218 AP29219	<b>X-SLIDE ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP30099 KIT</b> <b>SEE &gt; <a href="#">MR41.2670.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91350 (11.40” STROKE) REPLACES AP27865 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP91701 (4.300” STROKE) REPLACES AP30260 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 5 - RAP24640 (AP24640) ITEM 6 - RAP24641 (AP24641)
<b>MECHANISM</b> AP29415	<b>SINGLE CYLINDER ROOM EXTENSION – 18.0” STROKE – AP29414 KIT</b> <b>SEE &gt; <a href="#">MR41.1008.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP29841	<b>SINGLE CYLINDER ROOM EXTENSION – 18.0” STROKE – AP29840 KIT</b> <b>SEE &gt; <a href="#">MR41.1100.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP24635 (AP24635)
<b>MECHANISM</b> AP30563 AP30564	<b>DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 34.5” STROKE (WITH SYNC. CYLINDER)</b> <b>AP30562 KIT</b> <b>SEE &gt; <a href="#">MR41.2200.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90696 (36.0” STROKE) REPLACES AP19256 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.01” STROKE) REPLACES AP14368 HOSE ASSEMBLY_____ ITEM 2 - RAP52163 - REPLACES AP52163

<b>MECHANISM</b> AP31319 AP31320	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION – 25.0” STROKE (WITH SYNC. CYLINDER)</b> <b>AP31307 KIT</b> <b>SEE &gt; <a href="http://MR41.2680.HTML">MR41.2680.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.905” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP32275 AP32276	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION – 21.0” STROKE (WITH SYNC. CYLINDER)</b> <b>AP32274 KIT</b> <b>NO INFORMATION AVAILABLE.</b>
<b>MECHANISM</b> AP32334 AP32335	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) – AP32333 KIT</b> <b>SEE &gt; <a href="http://MR41.2680.HTML">MR41.2680.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91702 (34.0” STROKE) REPLACES AP31461 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90616 (8.240” STROKE) REPLACES AP18122 TUBE KIT_____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP32989	<b>DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP32988 KIT</b>  CYLINDER ASSEMBLY_____ RAP91705 (26.0” STROKE)–REPLACES AP35228 SYNCHRONIZING CYLINDER_____ RAP90440 (10.095” STROKE)–REPLACES AP16509 HOSE ASSEMBLIES_____ RAP24632 (AP24632)
<b>MECHANISM</b> AP36317	<b>SINGLE CYLINDER ROOM EXTENSION – 20.0” STROKE – AP36280 KIT</b> <b>SEE &gt; <a href="http://MR41.1200.HTML">MR41.1200.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91854 (22.5” STROKE) REPLACES AP36318 TUBE KIT_____ ITEM 2 - RAP90526 - REPLACES AP13592
<b>MECHANISM</b> AP36319	<b>SINGLE CYLINDER ROOM EXTENSION – 20.0” STROKE – AP36281 KIT</b> <b>SEE &gt; <a href="http://MR41.1100.HTML">MR41.1100.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91021 (27.0” STROKE) REPLACES AP28682 HOSE ASSEMBLIES_____ ITEM 3 - RAP24632 (AP24632) ITEM 4 - RAP24635 (AP24635)
<b>MECHANISM</b> AP37835	<b>CYLINDER ASSEMBLY – 24.5” STROKE</b>  CYLINDER ASSEMBLY_____ RAP92516 (24.5” STROKE) - REPLACES AP37835
<b>MECHANISM</b> AP38251 AP38252	<b>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP50576 KIT</b> <b>SEE &gt; <a href="http://MR41.2685.HTML">MR41.2685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)