

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "REXHALL WEST" (PAGE 4 OF 4)

PROCEDURE: SEE "REXHALL WEST" (PAGE 1 OF 4)

MECHANISM AP30563 AP30564	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 34.5" STROKE (WITH SYNC. CYLINDER) - AP30562 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90696 (36.0" STROKE) - REPLACES AP19256 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.01" STROKE) - REPLACES AP14368 HOSE ASSEMBLIES _____ ITEM 2 - RAP91708 - REPLACES AP20533</p>
MECHANISM AP31319 AP31320	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 25.0" STROKE (WITH SYNC. CYLINDER) - AP31307 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.905" STROKE) - REPLACES AP16509 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP32275 AP32276	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 21.0" STROKE (WITH SYNC. CYLINDER) - AP32274 KIT</p> <p>NO INFORMATION AVAILABLE.</p>
MECHANISM AP32334 AP32335	<p>UNIVERSAL SLIDE OUT ROOM EXTENSION - 20.0" STROKE (WITH SYNC. CYLINDER) - AP32333 KIT</p> <p>SEE MR41.2680 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90616 (8.240" STROKE) - REPLACES AP18122 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP32989	<p>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32988 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP91705 (26.0" STROKE) - REPLACES AP35228 - TWO USED SYNCHRONIZING CYLINDER _____ RAP90440 (10.095" STROKE) - REPLACES AP16509 HOSE ASSEMBLIES _____ RAP90872 (AP24632) - TWO USED</p>
MECHANISM AP36317	<p>SINGLE CYLINDER ROOM EXTENSION - 20.0" STROKE - AP36280 KIT</p> <p>SEE MR41.1200 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91854 (22.5" STROKE) - REPLACES AP36318 TUBE KIT _____ ITEM 2 - RAP90526 - REPLACES AP13592</p>
MECHANISM AP36319	<p>SINGLE CYLINDER ROOM EXTENSION - 20.0" STROKE - AP36281 KIT</p> <p>SEE MR41.1100 FOR DRAWING AND PART INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP91424 (AP24635)</p>
MECHANISM AP37835	<p>CYLINDER ASSEMBLY - 24.5" STROKE</p> <p>CYLINDER ASSEMBLY _____ RAP92516 (24.5" STROKE) - REPLACES AP37835</p>
MECHANISM AP38251 AP38252	<p>UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP50576 KIT</p> <p>SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>