

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "ROADMASTER CUSTOM MOTOR COACH"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM</b> <b>AP25730</b> <b>AP25731</b>	<b>VERTICAL ARM ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP25729 KIT</b>  <b>SEE MR41.2500 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91200 (10.172" STROKE) - REPLACES AP24733 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 6 - RAP91019 (3.935" STROKE) - REPLACES AP13180 <b>TUBE KIT</b> _____ RAP91224 - REPLACES AP23196 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90386 (AP24643) ITEM 5 - RAP91236 (AP24647)
<b>MECHANISM</b> <b>AP32458</b> <b>AP32459</b>	<b>LATERAL ARM ROOM EXTENSION - 20.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP32457 KIT</b>  <b>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91351 (6.775" STROKE) - REPLACES AP27997 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 3 - RAP90524 (2.385" STROKE) - REPLACES AP14881 <b>TUBE KIT</b> _____ ITEM 2 - RAP91774 - REPLACES AP28035 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP91574 (AP24627) ITEM 5 - RAP91574 (AP24627)
<b>MECHANISM</b> <b>AP32572</b> <b>AP32573</b>	<b>UNIVERSAL SLIDE OUT ROOM EXTENSION - 25.0" STROKE (WITH SYNC. CYLINDER) - AP32571 KIT</b>  <b>SEE MR41.2680 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509 <b>TUBE KIT</b> _____ ITEM 2 - RAP91703 - REPLACES AP31486 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP91421 (AP24818) ITEM 5 - RAP90872 (AP24632)