

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "RS MOTORHOMES"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM AP21070 AP21071</b>	<b>DUAL CYLINDER ROOM EXTENSION - 24.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP21069 KIT</b>  <b>SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 3 - RAP90473 (12.155" STROKE) - REPLACES AP13192 <b>TUBE KIT</b> _____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM AP30055</b>	<b>SINGLE CYLINDER ROOM EXTENSION - 30.0" STROKE - AP30054 KIT</b>  <b>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91805 (31.0" STROKE) - REPLACES AP28687 <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP90781 (AP24628) ITEM 4 - RAP90872 (AP24632)