

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "SCHUCK ENTERPRISES"

PROCEDURE:

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP37382	SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP39382 KIT SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 HOSE ASSEMBLIES _____ ITEM 3 - RAP90872 (AP24632) ITEM 4 - RAP90871 (AP24628)
MECHANISM AP38251 AP38252	UNIVERSAL STRAIGHT OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP39381 KIT SEE MR41.2685 FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)