

---

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "SKIPPERLINER IND. INC."

---

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM</b> <b>AP13666</b> <b>OR</b> <b>AP19321</b> <b>AP19322</b>	<b>DUAL CYLINDER ROOM EXTENSION - 36.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP13667 KIT</b>  <b>SEE MR41.2026 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ <b>ITEM 1 - RAP90518 (36.50" STROKE) - REPLACES AP15251</b> <b>SYNCHRONIZING CYLINDER</b> _____ <b>ITEM 3 - RAP90474 (14.630" STROKE) - REPLACES AP12484</b> <b>HOSE ASSEMBLIES</b> _____ <b>ITEM 2 - RAP90480 - REPLACES AP13252</b>
---	---