

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "STAR WAGGONS"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

MECHANISM AP22019 AP22020	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP22018 KIT</b></p> <p><a href="#">SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224</p> <p>SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.010" STROKE) - REPLACES AP14368 OR - RAP93556 (12.140" STROKE) - REPLACES AP49062</p> <p>TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP22025 AP22026	<p><b>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP22024 KIT</b></p> <p><a href="#">SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224</p> <p>SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509</p> <p>TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP33037	<p><b>SINGLE CYLINDER ROOM EXTENSION - 30.0" STROKE - AP44037 KIT</b></p> <p><a href="#">SEE MR41.1008 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365</p> <p>TUBE ASSEMBLIES _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP40943	<p><b>SINGLE CYLINDER ROOM EXTENSION - 30.0" STROKE - AP43929 KIT</b></p> <p><a href="#">SEE MR41.1006 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365</p> <p>TUBE ASSEMBLIES _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP42510	<p><b>SINGLE CYLINDER SLIM LINE ROOM EXTENSION - 30.0" STROKE - AP43299 KIT</b></p> <p>NO INFORMATION AVAILABLE.</p>
MECHANISM AP44654 AP44655	<p><b>DUAL CYLINDER ROOM EXTENSION - 34.5" STROKE (WITH SYNCHRONIZING CYLINDER) - AP44653 KIT</b></p> <p><a href="#">SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224</p> <p>SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90464 (14.010" STROKE) - REPLACES AP14368 OR - RAP93556 (12.140" STROKE) - REPLACES AP49062</p> <p>TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>
MECHANISM AP51686	<p><b>CYLINDER ASSEMBLY - 25.5" STROKE</b></p> <p>CYLINDER ASSEMBLY _____ RAP93555 (25.5" STROKE) - REPLACES AP51686</p>
MECHANISM AP53194 AP53195	<p><b>DUAL CYLINDER ROOM EXTENSION - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP53096 KIT</b></p> <p><a href="#">SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</a></p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90488 (35.0" STROKE) - REPLACES AP15224</p> <p>SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509</p> <p>TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>