

OEM Guide Page

HWH SpaceMaker Equipment for **STAR WAGGONS Vehicles**

(File: MR407000.DOC | Revised: 26APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM AP22019 AP22020	DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER) AP22018 KIT SEE > MR412011.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.010” STROKE) REPLACES AP14368 OR RAP93556 (12.140” STROKE) REPLACES AP49062 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP22025 AP22026	DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP22024 KIT SEE > MR412011.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP33037	SINGLE CYLINDER ROOM EXTENSION – 30.0” STROKE – AP44037 KIT SEE > MR411008.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90629 (30.5” STROKE) REPLACES AP17365 TUBE ASSEMBLY_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP40943	SINGLE CYLINDER ROOM EXTENSION – 30.0” STROKE – AP43929 KIT SEE > MR411006.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90629 (30.5” STROKE) REPLACES AP17365 TUBE ASSEMBLIES_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP42510	SINGLE CYLINDER SLIM LINE ROOM EXTENSION – 30.0” STROKE – AP43299 KIT NO INFORMATION AVAILABLE.

MECHANISM AP44654 AP44655	DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER) AP44653 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.010” STROKE) REPLACES AP14368 OR RAP93556 (12.140” STROKE) REPLACES AP49062 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP51686	CYLINDER ASSEMBLY 25.5” STROKE CYLINDER ASSEMBLY_____ RAP93555 (25.5” STROKE)-REPLACES AP51686
MECHANISM AP53194 AP53195	DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP53096 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252