

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TETON HOMES"

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM AP25518 AP25519</b>	<b>DUAL CYLINDER ROOM EXTENSION - 42.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP42751 KIT</b>  <b>SEE MR41.2011 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP90477 (43.0" STROKE) - REPLACES AP15668 <b>SYNCHRONIZING CYLINDER</b> _____ ITEM 3 - RAP90447 (17.100" STROKE) - REPLACES AP15687 <b>TUBE KIT</b> _____ ITEM 2 - RAP90481 - REPLACES AP15379
<b>MECHANISM AP42740</b>	<b>SINGLE CYLINDER ROOM EXTENSION - 28.0" STROKE - AP42374 KIT</b>  <b>SEE MR41.1100 FOR DRAWING AND PARTS INFORMATION.</b> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91209 (30.125" STROKE) - REPLACES AP28686 <b>HOSE ASSEMBLIES</b> _____ ITEM 3 - RAP91117 (AP24635)    ITEM 4 - RAP91178 (AP24636)