

# ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TRAIL WAGONS INC."

**PROCEDURE:**

1. Locate the HWH identification tag on the room extension mechanism to get the correct room extension part number.
2. Find the correct room extension part number in the left column below.
3. Refer to the proper parts page for general replacement parts information and item number arrangements.
4. Two cylinder room extensions with a synchronizing cylinder have two room extension part numbers. One number is for the left assembly, one is for the right assembly. If the room extension assembly originally had one number, that number is listed with the new numbers.

<b>MECHANISM AP24338</b>	<b>SINGLE CYLINDER ROOM EXTENSION - 14.0" STROKE - AP24337 KIT</b>  <a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91807 (15.0" STROKE) - REPLACES AP29366 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90871 (AP24628) ITEM 3 - RAP90872 (AP24632)
<b>MECHANISM AP29278</b>	<b>SINGLE CYLINDER ROOM EXTENSION - 24.0" STROKE - AP29277 KIT</b>  <a href="#">SEE MR41.1101 FOR DRAWING AND PARTS INFORMATION.</a> <b>CYLINDER ASSEMBLY</b> _____ ITEM 1 - RAP91021 (27.0" STROKE) - REPLACES AP28682 <b>HOSE ASSEMBLIES</b> _____ ITEM 4 - RAP90871 (AP24628) ITEM 3 - RAP90872 (AP24632)