

ROOM EXTENSION ASSEMBLIES GUIDE PAGE "TRIPLE E MFG." (PAGE 3 OF 3)

PROCEDURE: SEE "TRIPPLE E MFG." (PAGE 1 OF 3)

MECHANISM AP40753 AP40754	<p>UNIVERSAL LEVEL OUT - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41597 KIT</p> <p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 11 - RAP92261 (3.50" LIFT) - REPLACES AP40746 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER _____ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP43112 AP43113	<p>DUAL CYLINDER ROOM EXTENSION - 29.125" STROKE (WITH SYNC. CYLINDER) - AP33253 KIT</p> <p>SEE MR41.2020 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92524 (30.125" STROKE) - REPLACES AP43107 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90690 (11.780" STROKE) - REPLACES AP17966 TUBE KIT _____ ITEM 2 - RAP90658 - REPLACES AP18428</p>
MECHANISM AP43994 AP43995	<p>DUAL CYLINDER "HAT" ROOM EXTENSION - 22.0" STROKE (WITH SYNC. CYLINDER) - AP43993 KIT</p> <p>SEE MR41.2050 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90593 (22.5" STROKE) - REPLACES AP15384 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92522 (7.710" STROKE) - REPLACES AP43403 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>