

OEM Guide Page

HWH SpaceMaker Equipment for **VILLESSE SRL Vehicles**

(File: MR408815.DOC | Revised: 09MAY17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP20401</i>	<p>BED LIFT CYLINDER – 8.0” STROKE – AP20338 KIT</p> <p>CYLINDER ASSEMBLY_____ AP204001 (8.0” STROKE) – CONTACT HWH CORP.</p>
MECHANISM <i>AP20405</i>	<p>DOOR RAMP CYLINDER – 24.0” STROKE – AP20339 KIT</p> <p>CYLINDER ASSEMBLY_____ AP20405 (24.0” STROKE) – CONTACT HWH CORP.</p>
MECHANISM <i>AP20344</i>	<p>SINGLE CYLINDER ROOM EXTENSION – 32.0” STROKE – AP20343 KIT</p> <p>SEE > MR411006.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 – RAP90665 (32.5” STROKE) REPLACES AP18131</p> <p>TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252</p>