

ROOM EXTENSION ASSEMBLIES GUIDE PAGE

"WESTERN RECREATIONAL VEHICLES" (PAGE 2 OF 2)

PROCEDURE: SEE: "WESTERN RECREATIONAL VEHICLES" (PAGE 1 OF 2)

MECHANISM AP26584 AP26585	<p>DUAL CYLINDER LEVEL OUT ROOM EXTENSION - 31.0" STROKE (WITH SYNC. CYLINDER) - AP26583 KIT</p> <p>SEE MR41.2200 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91199 (32.0" STROKE) - REPLACES AP24262 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90442 (12.570" STROKE) - REPLACES AP16484 TUBE KIT _____ ITEM 2 - RAP91024 - REPLACES AP26587</p>
MECHANISM AP31677 AP31678	<p>UNIVERSAL FLAT OUT - 25.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP31676 KIT</p> <p>SEE MR41.2687 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91760 (36.0" STROKE) - REPLACES AP31645 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509 TUBE KIT _____ ITEM 2 - RAP92080 - REPLACES AP31651 HOSE ASSEMBLIES _____ ITEM 4 - RAP90321 (AP24653) ITEM 5 - RAP91560 (AP25680) LIFT MECHANISMS _____ ITEM 10 - RAP91746 (AP32555) ITEM 11 - RAP91748 (AP32556)</p>
MECHANISM AP33348 AP33349	<p>LATERAL ARM ROOM EXTENSION - 16.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP33347 KIT</p> <p>SEE MR41.2825 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91203 (6.150" STROKE) - REPLACES AP26255 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP91013 (1.810" STROKE) - REPLACES AP28566 TUBE KIT _____ ITEM 2 - RAP91226 - REPLACES AP27031 HOSE ASSEMBLIES _____ ITEM 4 - RAP91422 (AP24819) ITEM 5 - RAP91433 (AP23738)</p>
MECHANISM AP34218 AP34219	<p>UNIVERSAL LEVEL OUT ROOM EXTENSION - 25.0" STROKE (WITH SYNCH. CYLINDER) - AP34217 KIT</p> <p>SEE MR41.2683 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP91702 (34.0" STROKE) - REPLACES AP31461 LIFT CYLINDER ASSEMBLY _____ ITEM 10 - RAP91992 (2.75" LIFT) - REPLACES AP34390 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP90440 (10.095" STROKE) - REPLACES AP16509 LIFT SYNCHRONIZING CYLINDER _____ ITEM 11 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP91703 - REPLACES AP31486 HOSE ASSEMBLIES _____ ITEM 5 - RAP90872 (AP24632) ITEM 4 - RAP91421 (AP24818)</p>
MECHANISM AP35776	<p>CYLINDER ASSEMBLY - 60.0" STROKE - AP35775 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP92037 (60.0" STROKE) - REPLACES AP35775</p>
MECHANISM AP36890	<p>CYLINDER ASSEMBLY - 30.0" STROKE - AP36889 KIT</p> <p>CYLINDER ASSEMBLY _____ RAP92372 (30.0" STROKE) - REPLACES AP36890</p>
MECHANISM AP38383 AP38384	<p>UNIVERSAL LEVEL OUT - 26.0" STROKE (WITH SYNC. CYLINDER) - AP38677 AND AP42484 KIT</p> <p>SEE MR41.2690 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP92076 (30.5" STROKE) - REPLACES AP38072 LIFT CYLINDER ASSEMBLY _____ ITEM 14 - RAP92260 (2.75" LIFT) - REPLACES AP38604 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92469 (9.130" STROKE) - REPLACES AP39275 LIFT SYNCHRONIZING CYLINDER _____ ITEM 15 - RAP92316 - REPLACES AP38264 TUBE KIT _____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES _____ ITEM 4 - RAP90872 (AP24632) ITEM 5 - RAP91421 (AP24818)</p>
MECHANISM AP41562 AP41563	<p>DUAL CYLINDER ROOM EXTENSION - 30.0" STROKE (WITH SYNCHRONIZING CYLINDER) - AP41601 KIT</p> <p>SEE MR41.2005 FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY _____ ITEM 1 - RAP90629 (30.5" STROKE) - REPLACES AP17365 SYNCHRONIZING CYLINDER _____ ITEM 3 - RAP92077 (10.540" STROKE) - REPLACES AP37881 TUBE KIT _____ ITEM 2 - RAP90480 - REPLACES AP13252</p>